	• • •	CLASSIFIED MESSAGE	1 8	OUTING
DATE	2310Z 18 MAY 62	SECRET	1 2 3	4
TO :	DIRECTOR	EO 12958 3.3(b) (N)	UPERATIONA (1)>25%E19	L IMMEDIATE
ACTION:	DPD (1-2-3-4-5-6-7-8- S/C (11)	- 9-1Ø)	OPERATIONA	L IMMEDIATE
mro :	DCD TOR ØØ23Z 19 MAY 62	go!		IN 37127
TO XC		nfo \$1	O COTE	3393

1. ONE FLIGHT MADE THIS MORNING, ENDURANCE 1 HOUR AND 22 MINUTES. THE OBJECTIVE WAS TO REACH HIGHER SPEEDS AND MAKE THE USUAL STABILITY AND FLUTTER CHECKS AT THESE SPEEDS. AIR-CRAFT REACHED MACH 1.1 TO 1.3 IN CLIMB AND AFTER LEVELING OUT AT 41,000 FEET REACHED MACH 1.41. THEY HAVE NOW REACHED THE MAXIMUM SPEED FOR THIS ALTITUDE OF 400 KNOTS EAS AND 465 KNOTS IAS. SPEED POWER POINTS WERE TAKEN BOTH SUPERSONIC AND SUBSONIC. THE TERTIARY NACELLE DOORS WERE CLOSED FOR THE FIRST TIME WHICH REDUCED DRAG AND PERMITED THE HIGHER SPEED TO BE ATTAINED. DURING MANUEVER 1.5 G WAS REACHED AT 350 KNOTS. THE TAKE OFF WAS MADE AT 85,450 LBS WITH A C.G. POSITION OF 20.2 PERCENT.

MESSRS KIEFER, BEERLI AND PARANGOSKY

2. A SECOND FLIGHT WAS SCHEDULED BUT DURING THE POST FLIGHT INSPECTION IT WAS FOUND THAT THE THIN SKIN AT THE TRAILING

APPROVED FOR RELEASE DATE: AUG 2007

ATT N:

FROM:

SECRET

PAGE TWO

3393 IN 37127

EDGE OF BOTH VERTICAL FINS WAS CRACKING AND PULLING AWAY FROM
THE FIRST 3 ROWS OF RIVETS OVER APPROXIMATELY 30 PERCENT OF THE
SPAN. THIS WILL NECESSITATE A SMALL REDESIGN AND MODIFICATION.
THE FINS HAVE BEEN SHIPPED TO LAC FOR REPAIR THIS WEEKEND AND
THE NEXT FLIGHT IS SCHEDULED FOR TUESDAY 22 MAY. KELLY SAYS
THAT THEY WILL START TO MOVE UP IN ALTITUDE IN ORDER TO INCREASE
TRUE SPEED NEXT WEEK.

- 3. LAC WILL SHUT DOWN FLIGHT OPERATIONS THURSDAY 24 MAY FOR APPROXIMATELY 14 DAYS FOR RESEALING OF TANKS 1 AND 5.

 THE RUNWAY SHOULDERS WILL BE SLURRIED AT THIS TIME.
- A. THERE WERE FOUR UNIDENTIFIED AIRCRAFT IN THE FLIGHT TEST
 AREA TODAY. HOWEVER, WE DO NOT FEEL THAT ANY OF THEM WERE NEAR
 ENOUGH TO COMPROMISE SECURITY. THEY WERE APPARENTLY ALL
 TRANSIENTS NONE FROM
- TODAY. MR PAYNE BROUGHT UP THE QUESTION OF CONTRAILS AS DID
 GENERAL THOMAS POWER LAST WEEK. HE FURTHER SUGGESTED THE
 POSSIBILITY OF A STUDY AND TEST PROGRAM ON THIS PROBLEM UNDER
 DIRECTION OF DR DALE CORSON, DEAN OF ENGINEERING, CORNELL
 UNIVERSITY, UTILIZING THE TULLAHOMA FACILITIES. ALL OF THIS
 UNDER THE GUISE AND FUNDING OF THE B-70 PROGRAM. MR PAYNE SAID
 THAT HE WILL DISCUSS THIS AND A SECURITY MATTER WITH DR SCOVILLE
 AND MR KIEFER ONE DAY NEXT WEEK.

6	9		CALI	ED TO	STATE	THAT	B-66	MAINT ENANC	E
AND	SPARES	PROBLEMS	HAVE	BEEN	PLAGUIN	ig the	DROF	PROGRAM.	

SECRET

3393 IN 37127	PAGE THREE
HOWEVER, 7 SUCCESSFUL DROPS WERE MADE WITH THE NE	W 78 INCH
FIRST STAGE CHUTE LAST WEEK AND AS A RESULT HE HA	S DECIDED TO
GO "LIVE" NEXT WEEK. THEY HAVE NOW FOUND A HOLE	IN THE VERTICAL
STABILIZER OF THE B-66 WHICH MAY DELAY THINGS FUR	THER FOR A
FEW DAYS BUT WE ARE SENDING THE JUMPER,	DOWN
TO BE READY TO GO MONDAY. THE FIRST JUMPS WILL B	E MADE AT 25,00
FEET OPENING FOR HE FIRST STAGE AND 16,000 FEET OF	PENING FOR THE
MAIN CHUTE. HAS VISITED LAC TO DISCUSS THE	PROBLEMS
OF INTERFERENCE BETWEEN THE PARACHUTE PACK AND TH	E PRESSURE
SUIT. HE STATES THAT WITH A FEW MINOR MODIFICATION	ONS THE PROBLEM
WILL BE ELIMINATED.	
7. WE DISCUSSED THE ACQUISITION OF SUPPORT ALL	R CRAFT SPARES
PROBLEM WITH HOUSER WILSON WHO FEELS THAT WE HAVE	NOT BEEN USING
THE AUTHORIZED "RED LINE" PRIORITY ON OUR REQUEST:	s. He WILL
BE OVER TO HEADQUARTERS TO DISCUSS THIS. WE FURT	HER GOT INTO
THE FUEL FILTER PROBLEM AGAIN WITH NO RESOLUTION.	WE NEED
SOMEONE IN THE ACT WHO KNOWS MORE ABOUT FUEL FILT	er ing and
PUMPING THAN ANYONE DOES BEFORE WE CA	n resolve
THIS ONE. (SEE MY WIRE 15 MAY).	
- AND DET TO THE MERCACE OUT IN DE SEVEC ON	ı v

-END OF MSG-